



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

D205-634-111
Job Sheet 203965



Part No: D205-634-111

Job Qty: 1 pcs

Part Name: Skidtube with Run-on Landing Wearplates Fits LH or RH



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 11/29/19

Job Tracking No:

Due Date: 12/24/19

Created By: Marie Lajeunesse

Type: Stock

Description:

Note: DWG REV I SHEET 12 IPP revA 11.09.26 new issue EC verified by:DD IPP REV:B 12.01.23 AS PER ECN11-684 DD VERF:EC IPP REV:C 13.03.21 AS PER ECN13-544 DD VERF:JLM

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
110	Packaging 1 - Pick Kit	1 pcs	12/24/19		0.00	0.00	Packaging 1 - 1		
							Packaging 1 - 2		
							Packaging 1 - 3		
							Packaging 1 - 4		
							Packaging 1 - 5		
							Packaging 1 - 6		
							Packaging 1 - 7		
							Packaging 1 - 8		
							Packaging 1 - 9		
							Packaging 1 - 10		
							Packaging 1 - 11		
							Packaging 1 - 12		
							Packaging 1 - 13		
							Packaging 1 - 14		
							Packaging 1 - 15		
							Packaging 1 - 16		
							Packaging 1 - 17		
							Packaging 1 - 18		
							Packaging 1 - 19		
							Packaging 1 - 20		
							Packaging 1 - 21		
							Packaging 1 - 22		
							Packaging 1 - 23		
							Packaging 1 - 24		
							Packaging 1 - 25		
							Packaging 1 - 26		
							Packaging 1 - 27		
							Packaging 1 - 28		
							Packaging 1 - 29		
							Packaging 1 - 30		

Fg Dock



Dart Aerospace Ltd.
1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com

Container No: S242402



Part: D205-634-111

Job No: 203965

Serial No/Batch: S242402

Revision:

Inspector:

Exp Date:

Instructions: TC STC SH96-88 Issue 3, FAA STC SR00563NY 08/08/11, EASA ST

120 QC 4	1 pcs	12/24/19	0.00 0.00	Packaging 1 - 31					
				Packaging 1 - 32					
				Packaging 1 - 33					
				Packaging 1 - 34					
				Packaging 1 - 35					
				Packaging 1 - 36					
				QC 4 - 28					
				QC 4 - 58					
				QC 4 - 69					
				QC 4 - 9					
				QC 4 - 46					
				QC 4 - 68					
				QC 4 - 72					
QC 4 - 74									
QC 4 - 75									
QC 4 - 78									
130 Packaging 3-1 - Stock - B4B 1 pcs		12/24/19	0.00 0.00	Packaging 3 - 1 - B4B	JAB				
				Packaging 3 - 2 - B4B					
				Packaging 3 - 3 - B4B					
				Packaging 3 - 4 - B4B					
				Packaging 3 - 5 - B4B					
				Packaging 3 - 6 - B4B					
				Packaging 3 - 7 - B4B					
				Packaging 3 - 8 - B4B					
				Packaging 3 - 9 - B4B					
				Packaging 3 - 10 - B4B					
				Packaging 3 - 11 - B4B					
				Packaging 3 - 12 - B4B					
				Packaging 3 - 13 - B4B					
				Packaging 3 - 14 - B4B					
				Packaging 3 - 15 - B4B					
				Packaging 3 - 16 - B4B					
				Packaging 3 - 17 - B4B					
				Packaging 3 - 18 - B4B					
				Packaging 3 - 19 - B4B					
				Packaging 3 - 20 - B4B					
				Packaging 3 - 21 - B4B					
				Packaging 3 - 22 - B4B					
				Packaging 3 - 23 - B4B					
				Packaging 3 - 24 - B4B					
				Packaging 3 - 25 - B4B					
				Packaging 3 - 26 - B4B					
				Packaging 3 - 27 - B4B					
				Packaging 3 - 28 - B4B					
				Packaging 3 - 29 - B4B					
				Packaging 3 - 30 - B4B					
				Packaging 3 - 31 - B4B					
				Packaging 3 - 32 - B4B					
				Packaging 3 - 33 - B4B					
				Packaging 3 - 34 - B4B					
				Packaging 3 - 35 - B4B					
				Packaging 3 - 36 - B4B					
				135 DC - 1 - B4B	1 pcs	12/24/19	0.00 0.00	DC - 1 - B4B	DAS 21 9-59 DEC 1 9 2019
								DC - 2 - B4B	
				140 QC 21 - SA	1 pcs	12/24/19	0.00 0.00	QC 21 - SA - 21	
QC 21 - SA - 70	DAS 21 9-59 DEC 1 9 2019								
QC 21 - SA - 53									
Part Op 110 - Packaging1-2 (Pick Kit)					DAS 21 9-59				
Descriptions: 120 - (QC4- 100% Inspect kits for completeness)									

130 - (Identify as per dwg & Stock Location:) Identify and pack for shipping as per PPP D205-634-111 Location : FG073
135 - (Document Control) Photocopy bluefile & type labels per PPP D205-634-111 CHG 004
140 - (QC21- Final Inspection - Work Order Release)

Job BOM				
Part / Item	Component Name	Quantity	Operation	Container
D205-634-141	Replacement Skidtube with Run-on Landing Wearplates Fits LH or RH	1 pcs (1 ea)	110-Packaging 1 - Pick Kit	5236873
K10003	Saddle	1 pcs (1 ea)	110-Packaging 1 - Pick Kit	5221869

Job Allocations				
Operation	Component Part	Required	Inventory	Allocated
110-Packaging 1 - Pick Kit	D205-634-141	1	1	0
	K10003	1	3	0

Part Specifications				
Specifications could not be found.				

Plex 11/29/19 1:23 PM Dart.lajeunesse.marie

Entered: _____ Date: _____

WORK ORDER NON-CONFORMANCE / ROUTE UPDATE

NCR No. _____

Route update only ☐



Job: _____ Part No. _____		DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐		DEPARTMENT/PROCESS Skid-tube ☐ Cross tube ☐ Eng. (Non-AW) ☐ Engineering ☐ Machining ☐ Small Fab ☐ Prod. Eng. Coord. ☐ Water Jet ☐ Large Fab ☐ Finishing ☐ Rec/Store/Packaging ☐ Supplier ☐ Quality ☐																																																																													
Date :	Sequence #:	QTY Affected :		MRB (QS1042)																																																																													
Description Work Order Deviation				Disposition																																																																													
Root Cause <table><tr><td>Operator</td><td>☐</td></tr><tr><td>Manufacturing Process</td><td>☐</td></tr><tr><td>Equip/Tooling</td><td>☐</td></tr><tr><td>Handling/Preservation</td><td>☐</td></tr><tr><td>Material</td><td>☐</td></tr><tr><td>Product Improvement</td><td>☐</td></tr><tr><td>Process Improvement</td><td>☐</td></tr><tr><td>Human Factors</td><td>☐</td></tr></table>				Operator	☐	Manufacturing Process	☐	Equip/Tooling	☐	Handling/Preservation	☐	Material	☐	Product Improvement	☐	Process Improvement	☐	Human Factors	☐	FAULT CATEGORY <table><tr><td>Pressure/Forced</td><td>☐</td><td>Contamination</td><td>☐</td><td>Power Loss/Surge</td><td>☐</td><td>Positioned Wrong</td><td>☐</td></tr><tr><td>Bending</td><td>☐</td><td>Misaligned/off center</td><td>☐</td><td>Folio/Program</td><td>☐</td><td>Outside Tolerance</td><td>☐</td></tr><tr><td>Crushing</td><td>☐</td><td>BOM/Route</td><td>☐</td><td>Grain Direction</td><td>☐</td><td>Drawing</td><td>☐</td></tr><tr><td>Cracks</td><td>☐</td><td>Broken/Damage/Defect</td><td>☐</td><td>Weld</td><td>☐</td><td>Finish</td><td>☐</td></tr><tr><td>Crimp/Kink/Ripple/Wave/Twist</td><td>☐</td><td>Incomplete/Unclear Instructions</td><td>☐</td><td>Wrong Stock Pulled</td><td>☐</td><td>Part Lost/Missing</td><td>☐</td></tr><tr><td>Marks/Chatter</td><td>☐</td><td>Drill Holes</td><td>☐</td><td>Out of Sequence</td><td>☐</td><td>Misread</td><td>☐</td></tr><tr><td>Mislabeled</td><td>☐</td><td>Fit/Function</td><td>☐</td><td>Off-set/Set-up</td><td>☐</td><td></td><td></td></tr></table>						Pressure/Forced	☐	Contamination	☐	Power Loss/Surge	☐	Positioned Wrong	☐	Bending	☐	Misaligned/off center	☐	Folio/Program	☐	Outside Tolerance	☐	Crushing	☐	BOM/Route	☐	Grain Direction	☐	Drawing	☐	Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Finish	☐	Crimp/Kink/Ripple/Wave/Twist	☐	Incomplete/Unclear Instructions	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐	Marks/Chatter	☐	Drill Holes	☐	Out of Sequence	☐	Misread	☐	Mislabeled	☐	Fit/Function	☐	Off-set/Set-up	☐		
				Operator	☐																																																																												
				Manufacturing Process	☐																																																																												
Equip/Tooling	☐																																																																																
Handling/Preservation	☐																																																																																
Material	☐																																																																																
Product Improvement	☐																																																																																
Process Improvement	☐																																																																																
Human Factors	☐																																																																																
Pressure/Forced	☐	Contamination	☐	Power Loss/Surge	☐	Positioned Wrong	☐																																																																										
Bending	☐	Misaligned/off center	☐	Folio/Program	☐	Outside Tolerance	☐																																																																										
Crushing	☐	BOM/Route	☐	Grain Direction	☐	Drawing	☐																																																																										
Cracks	☐	Broken/Damage/Defect	☐	Weld	☐	Finish	☐																																																																										
Crimp/Kink/Ripple/Wave/Twist	☐	Incomplete/Unclear Instructions	☐	Wrong Stock Pulled	☐	Part Lost/Missing	☐																																																																										
Marks/Chatter	☐	Drill Holes	☐	Out of Sequence	☐	Misread	☐																																																																										
Mislabeled	☐	Fit/Function	☐	Off-set/Set-up	☐																																																																												
Completed By																																																																																	
Lead hand / Supervisor																																																																																	
QC / QA Coordinator																																																																																	